

BAUHAUS DESSAU

World Cultural Heritage since 1996

Engineering geological conditions and problem:

The building is founded in geotechnical unproblematic sands and gravels (Weichsel-glacial valley sand). The ground water level is about 2 m under ground. The area (city) is protected by a dam against high water of the river Mulde.



Bauhaus

Other information:

The considerable damages of the structural fabric do not result from engineer-geologic circumstances. The damages were recently removed by a comprehensive renovation.

References on studies already performed:

Source: Landesamt für Geologie und Bergwesen Sachsen-Anhalt.