

## PILGRIMAGE CHURCH ON THE WIES

World Cultural Heritage since 1983

### Engineering geological conditions and problems:

The baroque church is located on so-called Kames, consisting of a Pleistocene till i. e. stratified sand and gravels. The sediments are densely packed and show good load-bearing properties. Hence, foundation problems have not occurred.



*Total view of Wieskirche Church*



*Interior of the church*

### Other information:

The "pilgrimage church to the Scourged Saviour" ("Wieskirche") at the foot of the Alps is widely regarded as one of the most perfect examples of Bavarian rococo. It is one of the few churches of the 18<sup>th</sup> century preserved in its original style, described in art history as a true masterpiece.

### References on studies already performed:

Source: Bayerisches Geologisches Landesamt.